CHEVROLET—CENTRAL OFFICE

DIVISION OF GENERAL MOTORS CORPORATION **DETROIT 2, MICHIGAN**



TECHNICAL SERVICE BULLETIN

Technical Service Department



SUBJECT:

1961 CORVAIR "95" RAMPSIDE DOOR SAFETY

BULLETIN NO.

DR # 464

CATCH - STRIKER AND ADJUSTMENTS

SECTION T

TO:

ALL CHEVROLET DEALERS

DATE February 2, 1961

A new ramp door safety catch assembly incorporating increased metal thickness entered production on 11/28/60 effective at Flint with unit Serial #1R124F102775 at St. Louis with #1R124S107214.

Available in service parts is a new safety catch striker. The striker has a window type opening as illustrated in Figure 1 to minimize the possibility of the hook disengaging from the striker.

All units built prior to Serial #1R124F102775 and 1R124S107214 should have the early safety catch and striker replaced with the heavier safety catch and window type striker whenever a Corvair "95" Rampside is available at the dealership.

It is also recommended that both the main lock strikers and safety catch be adjusted, if necessary, to insure that ramp door strikers and the safety catch are positioned to provide adequante main lock and safety catch engagement.

To properly adjust the two main door locks, the strikers should be shimmed with spacers as required to provide 1/16" clearance between the front and rear face of the rampgate inner panel and the end of the strikers as shown in View A on the reverse side. The safety catch can be adjusted by installing 5/16" plain washers between the safety catch striker and rampside door to position the window in the striker in alignment to receive the safety catch as illustrated in Figure 1.

PARTS DATA

PART NO.

3789984 3796624 3778431 DESCRIPTION

Safety Catch Safety Catch Striker Spacer (as required) 5/16" plain washer

Turce

Director, Technical Service Department

JCP: dz

GSD 148-D

