## CHEVROLET-CENTRAL OFFICE

DETROIT 2, MICHIGAN



## TECHNICAL SERVICE BULLETIN

**Technical Service Department** 



SUBJECT:

HEAVY DUTY EXHAUST VALVE

1060 62 CORUATO

BULLETIN NO.

DR #551

1960-62 CORVAIR

SECTION

VI

TO:

ALL CHEVROLET DEALERS

DATE August 23, 1962

Introduction of the RPO 690 Turbocharged Corvair engine has made possible release of a new exhaust valve suitable for heavy duty usage. This valve consists of a heat resistant alloy head welded to a Silichrome "1" valve stem with built-in rotation features.

In the event of unsatisfactory exhaust valve life on 1960-62 Corvair standard or hi-performance (RPO 649) engines operating under sustained high-speed or heavy load conditions, the "Turbocharger" Exhaust Valve and Key Unit should be used for Service replacement.

This recommendation does not affect valve usage on Corvair "95" engines or normal replacement of valves on other Corvair engines.

## PARTS DATA

Exhaust Valve and Key Unit

Part Number	Description
3826492	Std. Size
3826493	.003 O. S.
3826494	.010 O. S.

Director, Technical Service Department

TRP: jg